






















A	4x45	x 14
B	1.4x25	x 21
C	3x25	x 118
D	6x50	x 4
E	3x20	x 26




№		PCS	 mm	 mm	 mm
1		2	19	52	1800
2		1	19	46	1800
3		23	19	92	1800
4		4	OSB	35	900
5		44	19	92	1200
6		2	19	92	1200
7	 	1	48	84	1290
8	 	1	38	38	1842
9	 	1	38	38	1842
10		2	OSB	800	1250
11		1	OSB	200	1250
12		2	13	92	1283
13		4	15	35	1800
14		1	13	92	1800
15		3	15	35	1250
16		1		585	1760
17		1		585	1760
18		2	15	35	855
19		42	19	92	284
20		1	15	69	1180
21		2	15	35	900
22		2	18	50	1047
23		2		1000	1310
24		6			
25		3			
26		1			

1






3




4

$$a=b$$




5

Int.




Ø6

Int.




Ext.




D_{x4}

13




A_{x2}






C_{x8}


Int.




6




7



8



9



10

