







M331G







$B \times 40$

5



$\sim 2\text{mm}$

No	PCS	DIMENSIONS		
1	22	38	38	1970
2	2	38	38	1006
3	47	19	92	1006
4	47	19	92	1970
5	10	12	35	150
A	22	 M4X70		
B	40	 M4X45		
C	517			



A	4x45	x 255
B	3x25	x 502
C	1.4x25	x 52
D	3x20	x 32
E	3x12	x 10
F	10x70	x 4
G	4x70	x 6
H	5x100	x 2
J	4x30	x 5

24

7

29

4K

2

9

34

5

30

11

6

44

18

19.2

19

19.3

19.1

19.4

14

32

10

13

15

8

28

26

33











3










25

4D



22

27


№		PCS	 mm	 mm	 mm
1		10		980	1900
2		2		980	1900
3		1		89	1960
4D		1		200	1814
4K		1		200	1814
5		1		748	1772
6		1		748	1772
7		2		500	2005
8		2		500	2005
9		1	30	60	1560
10		4		510	2150
11		2	15	15	712
12		4	40	60	1700
13		4	40	60	1450
14		1	40	60	1700
15		1	40	60	1450
16		2	17	47	980
17		4	17	47	1085
18		6	OSB	590	1810
19		6	OSB	390	1810
19.1		6	OSB	340	390
19.2		6	OSB	340	590


19.3		2	OSB	210	1810
19.4		2	OSB	210	340
20		4	OSB	35	1250
21		2	OSB	35	650
22		4	13	92	2160
23		10	15	35	2130
24		4	15	35	1835
25		4	17	47	1900
26		2	15	35	440
27		1	58	70	1650
28		2	15	75	145
29		5	15	35	1900
30		2	15	15	603
31		4	30	60	275
32		4	15	35	1575
33		1	58	70	1810
34		1	58	70	1810
35		14			
36		7			
37		8			
38		6			
39		6			
40		2			
41		1			
42		1			
43	1x10m   → 2x5,0m	2		1m	4,45m
		1		1m	4,45m
44		1		0,5m	4,45m

1





2





4

A_{x10}




36

B_{x16}

8


7








9

36

B_{x12}




5



6


A_{x8}



35

B_{x160}

13




12

14

12

15



13







B_{x30}

37


E_{x10}









A_{x2}








A_{x4}




10






12




B_{x4}

40

Ø12mm




40



B_{x4}


40





~61 mm

B_{x2}

40







15

