













M735










- A 4x70, T20 x 156
- B 5x100, T25 x 8
- C 4x50, T20 x 36
- D 4x30, T20 x 273
- E 4x40, T20 x 304
- F 3,1x15 x 6 pack
- G 4x12 T20 x 6
- H 10x60 x 14
- I 10x100 x 19






№	M735	PCS			
			mm	mm	mm
	Box 1				
1		8		1180	1900
2		1		1180	1900
3		1		772	1801
4		3		1180	1900
5		2			
5.1		1			


6		2		646	1770
7		2		646	1770
10		13	40	94	260
11		3	45	145	381
12		8	60	60	1810
13		2	20	120	774
15		4	13	92	774
16		1	13	92	1180
20		8	15	35	1900
21		2	15	35	630
22		1	60	87	1839
23		1	60	87	1839

24		1	60	87	925
27		8			1660
28		8			1250
32		2			
33		12			
34		14			
35		3			
36		3			
37		1			
38		1			
39		1			


	Box 2				
8		14	45	145	2021
9		12	20	120	2340
10		7	40	94	260
11		2	45	145	381
13		2	20	120	774
14		4	20	120	1180
16		3	13	92	1180
17		4	20	120	2053

18		4	16	96	1902
18.1		4	16	96	1902
19		8	13	92	1900
25		8	12	794	1001
26		4	12	1180	2002
29		5		1000	4280
30		6			
31		9			


1



B x8



Paint





E x32

A x8

2




Sealant
not
included




C x16

A x4




1

3




Sealant
not
included




A x12

C x16




4

$x=y$



$x=y$






5



Sealant
not
included


G x6

32







C x4

A x24




6






8




Align


34



E x32



A x4



9

1

H x10

33

8

D x40



2

I 15

11


9

10




Align



D x80



34




11




18

18.1

Cut







2





3



Cut






E x40








Align


E x40










Sealant
not
included




A x24






Sealant
not
included






A x8


19




21








E x112





19















F



30





31

